



FEB 2016

HARDWARE ADVISORY REMINDER

PXI Line Controllers: End-of-Life Status




Discontinued Product: PXI-style Line Controller
 Retired Notification: **July 2013**
 Replacement Product: LC2 Line Controller
 Systems Affected: Wolf and Coyote Sizing Lines

The new Line Controller hardware (LC2) uses solid state technology and is even more durable than the PXI predecessor.

No fans or filter maintenance - you can have confidence upgrading to the LC2 Line Controller.

Contact CFS today to schedule your upgrade. Prevent downtime by acting NOW!



The PXI type controller reached the retirement status in July 2013. For Wolf sites with outdated PXI hardware, an upgrade plan is **now urgent**.

- * The majority of PXI replacement parts are no longer available.
- * In the event of a PXI failure, a line will potentially be down until a new LC2 Line Controller is installed.
 - A CFS Service is visit required in this situation.
- * PXI controllers do not have to be replaced all at one time.
 - Incrementally replace some now and keep them as a spares for the others.
 - Phase out all of the PXIs according to your budget and time frame.

