

## SERVICE BULLETIN

**Title:** SBW081216 – PXI Line Controllers  
**Timeline:** Expired  
**Subject:** Wolf and Coyote Line Controllers (Sizing and Cutup Systems)

CFS released a new Line Controller (**LC2**) for the Wolf and Coyote Control Systems in **2013**. The previous model (**PXI**) is discontinued and replacement components are no longer available. Systems with PXI controllers need to be upgraded to the LC2 controllers.

Please contact CFS for a quote and service schedule. CFS can answer questions regarding the upgrade path, current software version, operating system and PXI line controller compatibility with LC2 controllers.



The LC2 is more durable, solid state, requires no fan or filter maintenance, and is installed as a replacement for the PXI controller. All of the current electronic circuitry in the Wolf and Coyote cabinets is compatible with the LC2.

**Requirements:**

- Software Version: Wolf 3.5 or higher; Coyote 1.5 or higher.
- PXI hardware (ram, flash, power supply) assessment for compatibility.